




























CHISELS AND GOUGES
BURINS ET GOUGES
CINCELES Y GUBIAS



			
3 mm 03-071-01	3 mm 03-072-01	3 mm 03-073-01	3 mm 03-074-01
			
4 mm 03-071-02	4 mm 03-072-02	4 mm 03-073-02	4 mm 03-074-02
			
5 mm 03-071-03	5 mm 03-072-03	5 mm 03-073-03	5 mm 03-074-03
			
6 mm 03-071-04	6 mm 03-072-04	6 mm 03-073-04	6 mm 03-074-04
 03-071-13 13.5 cm	 03-072-13 13.5 cm	 03-073-17 17 cm	 03-074-17 17 cm
Partsch			

 03-075-15 15 cm Freer	 4mm 03-076-16 16 cm Freer	 03-077-12 12 cm Passow	 03-078-16 16 cm Lucas	 3 mm 03-078-01	 5 mm 03-078-02
--	---	---	--	--	--